

Region 3 GPRA Baseline RCRA Corrective Action Facility

KLI, Inc. (Formerly: Keller Ladders, Inc.; Keller Aluminum)


16174 Industrial Drive

Milford, VA 22514

Congressional District 1

EPA ID #: VAD052356623

Last Updated: July 1, 2005



Current RCRA CA Activities

The Virginia Department of Environmental Quality's (DEQ) is the lead agency for oversight of RCRA Corrective Action work at the facility. The DEQ and the facility are in the process of establishing the mechanism (i.e., a permit) for conducting RCRA Corrective Action activities.

The facility submitted on October 23, 2001, a RFI Data Presentation Report. The DEQ will review the RFI Data Presentation Report and provide comments to the facility.

A post-closure care permit was issued on September 19, 1997 for a hazardous waste surface impoundment with wastes closed in place. The permit was the subject of an appeal by the facility, however, in November 2004 the appeal was withdrawn. The facility submitted a new post-closure care permit application in May 2005 which included HSWA Corrective Action. Upon final review of the new permit application, the DEQ will revoke the current post-closure care permit and reissue a new one. Groundwater is being monitored quarterly and the results submitted to the DEQ pursuant to the post-closure care permit. Most recently, the DEQ has completed its review of the 2002 Annual Groundwater Monitoring Report.

Site Description

The facility, located south of the town of Milford in Caroline County, Virginia, consists of a 21.33 acre parcel bounded by Industrial Drive (Route 640) to the west, Route 773 to the south, Hoover Wood Products to the east and Jones Chemical to the south.

During approximately 1968 to 1988, the following three businesses were operated at the facility: Keller Extrusions of Virginia, Inc., Keller Building Products of Virginia, Inc., and Keller Ladders of Virginia. Management of wastewater prior to the construction of a surface impoundment in 1977 is unclear. The property contains a drainage ditch located next to the surface impoundment and parallel to Route 773. The drainage ditch contains two drains that are constructed below Route 773 and discharge into neighboring wetlands.

The property contains a closed surface impoundment that is subject to a RCRA post-closure care permit issued September 19, 1997 by the DEQ.

RCRA CA Milestones

EPA Region III completed a RCRA Facility Assessment (RFA) in January 1989. On October 23, 2001, KLI, Inc. submitted an independent investigation report on the entire site to EPA Region III. The report recommends the following actions:

- Remove and dispose of sludge from an outdoor sump (SWMU #8)
- Remove and dispose of wastewater and sludge from two concrete holding tanks (SWMU #11)
- Complete a site wide risk assessment to determine whether site-wide closure can be obtained.

On December 4, 2001, EPA and DEQ met with Keller representatives to assess the work done by Keller's consultant, discuss information needed to complete the environmental indicators, and discuss process options to obtain the information.

As of March 7, 2003, the lead authority for RCRA Corrective Action at the facility was transferred from EPA Region III to DEQ. Representatives of DEQ and KLI, Inc. met on May 20 2003, to discuss the change in lead agency and necessary actions for continued progress of RCRA Corrective Action work at the facility.

Environmental Indicator Status

Under the Government Performance and Results Act (GPRA), EPA has set national goals to address high priority RCRA Corrective Action facilities by the year 2005. EPA is evaluating two key indicators for each facility: Current Human Exposures Under Control and Migration of Contaminated Groundwater Under Control. This facility is one of EPA Region III's high priority facilities and falls under this initiative. As of September 26, 2003 the current evaluation of Environmental Indicators for this facility is as follows:

- *Human Exposures Controlled Determination:* Based upon available information, the Human Exposures are Controlled. Please refer to form CA725 dated September 26, 2003 for more details.
- *Release to Groundwater Controlled Determination:* Based upon available information, Groundwater Releases are Controlled. Please refer to form CA750 dated September 25, 2003 for more details.

Contaminants

Contaminants found in the groundwater and soil include chromium and low levels of chlorinated organics.

Institutional Controls

A Deed Notice is in place identifying the location of the hazardous waste surface impoundment closed with waste in place as a landfill.

Community Involvement

Citizens' questions and concerns may be directed to the contact below. Also, the Administrative Record containing relevant information is available for public review at the following location(s):

Virginia Department of Environmental Quality
629 East Main Street
Richmond, Virginia 23219

KLI, Inc.
VAD052356623
July 1, 2005 RCRA CA Fact Sheet
Page 3 of 4

PHONE: (804) 698-4026
CONTACT: Matthew M. Stepien

Government Contacts

The Commonwealth of Virginia has the lead authority for this project. Please contact the state project manager listed below for details on this project or the contents of this fact sheet.

DEQ Project Manager

Matthew M. Stepien
Virginia Department of Environmental Quality
P.O. Box 10009
Richmond, VA 23240-0009
Phone: (804) 698-4026
Email: mmstepien@deq.virginia.gov

EPA Project Manager

Diane Schott - 3WC23
U.S. Environmental Protection Agency - Region III
1650 Arch Street
Philadelphia, PA 19103-2029
Phone: (215) 814-3430
Email: schott.diane@epa.gov

For more information about EPA's corrective action program, including Environmental Indicators, please visit EPA's web site at: www.epa.gov/reg3wcmd/correctiveaction.htm

Facility Contact

The facility contact is:

Tom L. Green
President, CEO
KLI, Inc.
c/o USI Properties, Inc.
950 E. Paces Ferry Road, Suite 2110
Atlanta, Georgia 30326-1125
Phone: (404) 364-6321

Factsheet Updates

The previous factsheet was updated January 2005. The next update is scheduled for December 2005. Previous factsheets may be obtained through the listed contacts.